

STATUS OF THE CLAIMS

Claims 1-16 are pending. Claims 9, 11 and 14 have been amended.

REMARKS

Pursuant to 37 CFR § 1.121, the above amendments are marked on separate sheets entitled "VERSION WITH MARKINGS TO SHOW CHANGES MADE" following these remarks.

The specification in column 1, line 63 has been amended by replacing the erroneous recitation of "valve 12a" with -- valve 12b --. Support for this amendment can be found in FIG. 1C which shows fluid (depicted by the bolded arrow) entering the valve assembly 10 through valve 16a and exiting the valve assembly 10 through valve 12b. Hence, no new matter is believed entered by this amendment.

The specification in column 3, line 21 has been amended by replacing the erroneous recitation of "A-A" with -- 3B-3B --. Support for this amendment can be found in FIG. 3A which shows only the section line 3B-3B. Hence, no new matter is believed entered by this amendment.

The specification in column 4, lines 16-19 has been amended by replacing the erroneous recitation "Fluid entering any of the ports encounters a chamber and channels leading to three diverter valves." with -- Fluid entering any of the ports encounters a chamber and channels leading to *at least two* diverter valves. *Fluid entering port 52, for example, encounters chamber 62 and channels leading to diverter valves 70 and 72.* -- Support for this amendment can be found in FIG. 3A. Hence, no new matter is believed entered by this amendment.

The specification in column 4, line 30 has been amended by replacing the erroneous

recitation of "A-A" with -- 3B-3B --. Support for this amendment can be found in FIG. 3A which shows only the section line 3B-3B. Hence, no new matter is believed entered by this amendment.


Claims 9 and 11 have been amended to correct typographical/spelling errors. In particular, the term "exists" recited in claims 9 and 11 has been replaced with the term -- exits --. Support for these amendments can be found in column 4, lines 19-59. Hence, no new matter is believed entered by this amendment.

Claim 14 has been amended to correct indefiniteness in the recitation of "between third and said second chamber." In particular, the definite article "said" was inadvertently omitted between the terms "between" and "third" in this recitation. Since the "third chamber" element is positively recited for the first time in claim 1, from which claim 14 indirectly depends, the definite article "said" should have been recited between the terms "between" and "third" in claim 14 to refer back to the "third chamber." No new matter is believed entered by this amendment.

It is respectfully submitted that claims 1-16 are in condition for allowance, early notification of which is earnestly solicited. Should there be any questions or other matters whose resolution may be advanced by a telephone call, the Examiner is cordially invited to contact Applicant's undersigned attorney at his number listed below.

No fee is believed due as a result of this communication. The Commissioner, however, is hereby authorized to charge any other fees which may be required or credit any overpayment to Deposit Account No. 04-1679.

Respectfully submitted,



Paul A. Schwarz, Esq.
Reg. No. 37,577

Duane, Morris & Heckscher LLP
100 College Road West, Suite 100
Princeton, New Jersey 08540
(609) 919-4408
(609) 919-4401 - facsimile

VERSION WITH MARKINGS TO SHOW CHANGES MADE

The following marked-up specification and claims correspond to the replacement specification and claims of this amendment.

Last paragraph starting at line 46 of column 1:

Fluid can flow through the prior art valve assembly 10 depicted in FIG. 1A in any one of the three directions depicted in FIGS. 1B-1D. The fluid flow is represented by arrows 25 in these figures. In FIG. 1B, which represents the forward product flow through the column, valve 14a is opened allowing the fluid to flow from the process piping into the valve assembly 10. Valve 16a is also opened allowing the fluid to flow into the chromatography column (not shown). The fluid returns from the chromatography column passing through valve 16b and reentering the valve assembly. The fluid leaves the valve assembly passing through valve 14b on its path back to the process piping. Valves 12a and 12b remain closed during this process. According to the reverse process flow depicted in FIG. 1C, fluid entering the valve assembly 10 from the process piping can flow through valves 12a and 16b into the column, returning from the column through valve 16a, and exiting the valve assembly through valve [12a] 12b back through the process piping. Valves 14a and 14b remain closed during this process. The column may be bypassed altogether according to the process flow depicted in FIG. 1D, where the liquid entering into the valve assembly from the process piping encounters opened valves 12a, 14a, 12b and 14b, exiting the valve assembly without entering the chromatography column which remains inaccessible by closing valves 16a and 16b.

The fifth full paragraph of column 3 starting at line 20:

FIG. 3B is an enlarged cross-sectional view through line [A-A] 3B-3B of FIG. 3A;

The first full paragraph of column 4 starting at line 6:

Referring now to FIG. 3A, there is shown a top view of the valve assembly, minus the manual bonnets and with a partial cross-sectional view of the underlying channel network drawn in with broken lines. As can be seen in this figure, ports 50, 52, 54 and 56 are arranged at angles of approximately 90° with respect to each other on opposing ends of the octagonal base section of the valve assembly. Each port opens into a chamber in the valve assembly 30—port 50 opening into chamber 60, port 52 opening into chamber 62, port 54 opening into chamber 64, and port 56 opening into chamber 66. Fluid entering any of the ports encounters a chamber and channels leading to [three] at least two diverter valves. Fluid entering port 52, for example, encounters chamber 62 and channels leading to diverter valves 70 and 72. Fluid entering port 50, for example, encounters chamber 60 and channels leading to diverter valves 70, 76 and 78. The smooth and tortuous network of passageways that lead through the valve assembly connect the ports with the chambers and valves in a such a way that the valve assembly is fully drainable as will be later explained. The flow of the fluid is controlled by the diverter valves 70, 72, 74, 76, 78 and may be adjusted to permit specific flow directions which, in combination with the smooth and tortuous passageways, eliminate dead-legs from the system.

The second full paragraph of column 4 starting at line 28:

Referring now to FIG. 3B, there is shown an enlarged cross-sectional view of the valve

assembly through line [A-A] 3B-3B of FIG. 3A. As can be seen in the figure, port 50 opens into chamber 60. A passageway 55 leading to diverter valve 76 can also be seen in this figure.

Chamber 60 is connected to chamber 64 via diverter valve 78. The passageway that connects these two chambers is inclined, rising sharply before encountering diverter valve 78 and then falling sharply after encountering the valve. The angle of inclination 63 measured from either side of the diverter valve 78 is approximately 30°. In chamber 64, a passageway 65 leading to diverter valve 74 can be seen. Finally in this figure, port 54 can be seen as opening into chamber 64.

9.(AMENDED) The diverter valve assembly of claim 1, wherein fluid flowing in a first direction enters said valve assembly through said first port, passes through said first chamber, is directed across said first diverter valve into said second chamber, exits said valve assembly through said second port, reenters said valve assembly through said fourth port, passes through said fourth chamber, is directed across said third diverter valve, passes through said third chamber, and [exists] exits said valve assembly through said third port.

11.(AMENDED) The diverter valve assembly of claim 1, wherein fluid flowing in a second direction enters said valve assembly through said first port, passes through said first chamber, is directed across said fourth diverter valve into said fourth chamber, exits said valve assembly through said fourth port, reenters said valve assembly through said second port, passes through said second chamber, is directed across said second diverter valve, passes through said third chamber, and [exists] exits said valve assembly through said third port.

1875	1876	1877	1878	1879	1880	1881	1882	1883	1884	1885	1886	1887	1888	1889	1890	1891	1892	1893	1894	1895	1896	1897	1898	1899	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	1920	1921	1922	1923	1924	1925	1926	1927	1928	1929	1930	1931	1932	1933	1934	1935	1936	1937	1938	1939	1940	1941	1942	1943	1944	1945	1946	1947	1948	1949	1950	1951	1952	1953	1954	1955	1956	1957	1958	1959	1960	1961	1962	1963	1964	1965	1966	1967	1968	1969	1970	1971	1972	1973	1974	1975	1976	1977	1978	1979	1980	1981	1982	1983	1984	1985	1986	1987	1988	1989	1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099	2100	2101	2102	2103	2104	2105	2106	2107	2108	2109	2110	2111	2112	2113	2114	2115	2116	2117	2118	2119	2120	2121	2122	2123	2124	2125	2126	2127	2128	2129	2130	2131	2132	2133	2134	2135	2136	2137	2138	2139	2140	2141	2142	2143	2144	2145	2146	2147	2148	2149	2150	2151	2152	2153	2154	2155	2156	2157	2158	2159	2160	2161	2162	2163	2164	2165	2166	2167	2168	2169	2170	2171	2172	2173	2174	2175	2176	2177	2178	2179	2180	2181	2182	2183	2184	2185	2186	2187	2188	2189	2190	2191	2192	2193	2194	2195	2196	2197	2198	2199	2200	2201	2202	2203	2204	2205	2206	2207	2208	2209	2210	2211	2212	2213	2214	2215	2216	2217	2218	2219	2220	2221	2222	2223	2224	2225	2226	2227	2228	2229	2230	2231	2232	2233	2234	2235	2236	2237	2238	2239	2240	2241	2242	2243	2244	2245	2246	2247	2248	2249	2250	2251	2252	2253	2254	2255	2256	2257	2258	2259	2260	2261	2262	2263	2264	2265	2266	2267	2268	2269	2270	2271	2272	2273	2274	2275	2276	2277	2278	2279	2280	2281	2282	2283</
------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	--------